

**Recommended Optional Accessories**

**Scanners**



The Welch Allyn ImageTeam™ 3800LR  
High Performance Linear Imager



Symbol Wearable Scanning System



Hand-Held 7400 Windows CE Scanner



Symbol 8100 PDT - Windows CE Scanner



HandKey Biometric Hand Scanner

**Bar-Code Printers**



Eltron TLP 3742 Thermal Transfer  
Barcode Printer



Zebra Z 4000

**Wireless Network Devices**



Cisco Aironet Access Point 350 Series



Cisco Aironet PCMCIA Card



Cisco Aironet PCI Card

**SoftWare Additions**



CribMaster Preventive Maintenance



CribMaster Remote Issue

**System Expansion**



CM Data Warehouse  
Easily link multiple facilities to a  
single data source.

**Recommended Minimum System Requirements**

- Pentium 90 or better running Windows 95/98/ME/XP/2000 or NT 4.0
- 32 Meg of memory (64 Meg recommended)
- 30 Meg of free disk space
- 15" SVGA monitor (17" monitor recommended)
- CD ROM drive

